

St. Boniface Parish Projects List 2018

We, as parishioners, look to share our time, talent, and treasure with our parish as we continue with keeping our buildings and grounds in good condition. We must also remember that funding for the items listed may not have been secured. As such, a funding source will need to be identified prior to engaging in many of these projects.

Church

1. North entry – handrails needed. **This project is currently under construction by a volunteer.**
2. Joseph Alter & Good Shepard Statue out of plumb need support, shim.
3. Drywall cracks: 4 or 5 locations - Tape, sand & paint.
4. Flooring under pews – seams starting to separate and lift, need repairs or replace.
5. Paint peeling off church siding, at east Fellowship Hall door & near Sacristy entry.
6. Church East & West entries stairway & ramp railing sandblast/strip for repaint.
7. Main entrance to church (east door along Co. Rd. 92) repairs.
8. Spray foam ductwork in church basement to reduce heating/cooling costs.
9. **Sidewalk repairs/replacement.**
10. Fellowship Hall floor tile cracks: kitchen, entry ways, men's room.
11. Water infiltration into church basement.
12. Carpet in the Fellowship Hall, target replacement in 2022.
13. North entrance to church needs repair or rebuild
14. **Church parking lot resurface/repair**

Rectory

15. Water infiltration/seepage in basement.
16. Front door repair/replacement.
17. Spray foam ceiling in basement to reduce dust infiltration.
18. Landscape of hill area along Main Street and school garage driveway.

School

19. Gym clean and repaint walls.
20. Ceiling tile issues: gym, corridor & Classrooms -falling off and stained.
21. Kitchen folding doors need repair/replacement, broken slates and hardware
22. Kitchen sink and faucet replacement (4 needed).
23. **Gym floor tile and trim replace.**
24. Kitchen and entry way floor tile need to be replaced.
25. Occupancy sensors for hallways and bathrooms, recommended by energy audit in 2010.
26. Bathrooms floor & wall tile replacement, repaint rooms.
27. Bathrooms doorways need enlargement to accommodate wheel chair access.
28. Kitchen counters, replace – may need to go with stainless steel.
29. Replacement A/C units for the classrooms, 20yrs. old and not efficient.
30. Insulate north classrooms of school building

Cemetery

31. Repair south concrete wall where vehicle struck it
32. Fence sandblast/strip for repaint, rusting, especially northwest and main gate areas or replace with different fence, portions sunken into ground
33. Need a "Rules" sign made and posted at gate entrances and north side of cemetery
34. **Repair/reset sunken, leaning, and uneven headstones and markers, fill in sunken areas. Ongoing issue.**